

# Activation Background in Counters

Activated quadrupole steel

- Periods of sustained high losses
- Large beam “accident”
  - radiation mostly
- Lose timing info
- Contaminated measurement

Majority 2/4 coincidence

- + Reduces contamination
- + Reduces overall rate
- Insensitive to single particles

## Counters

